

Martin Luther King, Jr. Drive at Business 40 Eastbound Ramps

2015 Traffic Conditions


40 No Build Option




Existing Roadway Network




40 Fully Closed (2 Year Option)



With Intersection Improvements



40 Partially Closed (6 Year Option)



With Intersection Improvements

